		•
7	7	1
÷	_	-

STATE OF CONNECTICUT

ONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106 (203) 566-3005

ISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

in the rear.

FOR OFFICE	USE	ONLY		
TOWN NO.: UTM: 18/_, QUAD:	//-		TE NO.: -//	
DISTRICT:	5	NR:	ACTUAL POTENTIAL	

DENTIFICATION German Evangelical
1. BUILDING NAME: Common: St. Paul's Lutheran Church Historic: Lutheran Church
2. TOWN/CITY: Middletown VILLAGE: COUNTY: Middlesex
3. STREET & NUMBER (and/or location): 76 High Street
4. OWNER(S): Lutheran Church in America . PUBLIC X PRIVATE
5. USE: Present: Religious Historic: same
6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: x yes no Interior accessible: xyes, explain at services no
ESCRIPTION
7. STYLE OF BUILDING: Late Gothic Revival DATE OF CONSTRUCTION: 1896
8. MATERIAL(S) (indicate use or location when appropriate): clapboardasbestos sidingwood shingleasphalt sidingboard & battenstuccoaluminum sidingconcrete: type:x cut stone: type: rusticatedbrownstone window sills, water table, and front foundationwood frame:post and beamballoonx load bearing masonrystructural iron or steelother:
10. ROOF: type:
xgableflat mansardmonitor sawtoothgambrelshed hipround other
material:
wood shingleroll asphalt tinx slateasphalt shinglebuilt up tileother: Sanctuary 35'x65'; rear
11. NUMBER OF STORIES: 21 APPROXIMATE DIMENSIONS: addition 32'x70'
12. CONDITION: Structural: excellent good fair deteriorated excellent good fair deteriorated
13. INTEGRITY: Location: x on original site
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES: barnshedgaragex other landscape features or buildings: shrubs, foundacarriage houseshopgardention plantings; flagstone in front
15. SURROUNDING ENVIRONMENT: open landwoodlandx residentialscattered buildings visible from sitecommercialindustrial ruralhigh building density
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: St. Paul's Lutheran Church is sited of the west side of High Street in a residential area two blocks south of the Wesleyan Univer-

sity campus. Closely surrounded by 2 and 3-story residences, the remainder of its narrow sloping lot is used by a 70' long added parish hall that extends all the way to Oak Street

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

Brass lantern in recessed center-front archway
Flared eaves on gable roof
Square center-front tower with belfry and slate roof; Celtic cross

Architect: P.H.J. Krulder Builder: 18. HISTORICAL OR ARCHITECTURAL IMPORTANCE: The cornerstone of the German Evangelical Lutheran Church was laid on Sunday, July 12, 1896; the building was put into use later that year. The pastor at that time was the Rev. Carl Blecher. For some years services were conducted in German and English. Gradually the church moved closer to the mainst of American Lutheranism. Today the church is under the aegis of the Lutheran Church is America. With the exception of a period of time in 1955, when the interior was being revated after a serious fire, the same building has been in continuous use for more than eighty years. This well-designed late Gothic Revival church displays a number of individualistic feaves of the gable roof are gently flared; buttresses in brick of a brighter hue; the eaves of the gable roof are gently flared; buttresses in brick support and segment the walls of the sanctuary. To meet the needs of a growing congregation a long, narrow, be two-story parish hall was added to the rear in 1955. This masonry building, with its brick and brownstone walls, and its gable and tower covered with slate, gives a feeling of both substance and stability.	ream n eno- cea- che corick
Covered with Size, 82.05	
PHOTOGRAPH photographer:Elizabeth Loomis date:12/78view:west negative on file:Rol1 56, #22A	
COMPILED BY: name: Roger Sherman date: 9/78 organization: Greater Middletown Preservation Trust organization: 27 Washington St., Middletown, Ct. 06457	
19. SOURCES: Middletown Tax Records; Middletown Land Records; The Middletown Tribune, 7/12/1896	7
20. SUBSEQUENT FIELD EVALUATIONS:	
21. THREATS TO BUILDING OR SITE:	